SBC Telecommunications, Inc 1401 I Street, N.W., Suite 1100 Washington, D.C. 20005 Phone 202 326-8884 Fax 202 408-4801



September 13, 2000

SEP 13 2000
SEP 13 2000
SEP 13 2000
SEPERAL COMMUNICATIONS COMMUNI

Mr. Dale Hatfield Office of Engineering and Technology Federal Communications Commission 445 12<sup>th</sup> Street, SW, Room 7-A-340 Washington, DC 20554

Re: Final Service Disruption Report

Dear Mr. Hatfield:

Pursuant to the requirements established in the Report and Order in CC Docket No. 91-273 (Amendment of Part 63 of the Commission's Rules to Provide for Notification by Common Carriers of Service Disruptions), PACIFIC BELL submits the attached Final Service Disruption Report associated with a service disruption in Central Valley, California on August 14, 2000.

An Initial Service Disruption Report was faxed to the FCC's Monitoring Watch Officer on that date.

Please stamp and return the provided copy to confirm your receipt. Please contact me if you have questions regarding this service disruption.

Sincerely,

**Enclosures** 

CC: Bob Kimball Kent Nilsson



A member of the SBC global network

Retention Period: 6 Years		FCC SERVICE DISRUPTION REPO								
Type of Repo	rt:	☐ Initi	al Report		Update	⊠ Final				
Occurred:	Date:	08/14/2000	Time: 15	5:50 PDT		50,000 or More ( 30,000 - 49,999				
Ended:	Date:	08/17/2000	Time: 15	5:58 PDT	$\overline{\boxtimes}$	Fire incident ≥ 1. Special Offices/l	000 lines			
Duration (in n	ninutes	s):	4,328 minu	tes		☐ 911 ☐ Major/Mediu ☐ NCS Reque	m Airport			
Geographic Area Affected: Central Valley, California										
Estimated Customers Affected: 1,802										
Type(s) of Services Affected:										
Estimated Blocked Calls: Unknown. Approximately 150 Customer Reports were received.										
<b>Apparent or Known Cause of the Outage:</b> At 15:50 PDT, on Monday, August 14, 2000 a wildfire burned two aerial exchange cables at three locations that had 1,802 working pairs South of Union School Road between Old Oregon Trail and Interstate 5 near the town of Central Valley, California. The exchange cables serve three pair gain facilities supporting eleven SLC 96 (Subscriber Loop Carrier) and seven SLC Series 5 systems. Restoration crews were prevented from entering the area until Tuesday, August 15.										
There were no local media co		•	wering Poir	nts (PSAP's	s) affected	d by the event.	There was			
Root Cause is	Extern	al Environme	ent - Fire.							
Name and Type of Equipment Involved: Copper Exchange Cables										
Specific Part of Network Involved: Local										

**Methods used to Restore Service:** Construction personnel replaced ten telephone poles. Approximately 1,500 feet of 600 pair copper cable and 1,500 feet of 900 pair copper cable were strung on the poles and a section roll was performed. When commercial power was restored to the area the remote terminals were brought back on line and service was restored.

Steps Taken to Prevent Recurrence: None

Applicable Best Practices: Pacific Bell reviewed the <u>Keeping the Network Alive and Well:</u> Solving the Problem of Cable Dig-Ups, dated February 1996 and evaluated all recommendations and best practices. Based on the Root Cause analysis there is no specific focus area that covers wild fires.

**Best Practices Used:** Pacific Bell observes those practices that are consistent with providing outstanding customer service.

Analysis of Effectiveness of Best Practices: Not Applicable.

Prepared by: Jim Lankford Telephone: 210-886-4589

Date submitted: 09/13/2000 Time: 13:30 CDT

NO.809 P.2/2

00-13/

## PACIFIC BELL.

A member of the SBC global network

Retention Pariod:	6 Years		FCC SE	RVICE D	ISRUP'	TION REF	PORT			
Type of Repo			ıl Report	Up	odate	☐ Final				
Occurred:		08/14/2000	Time: 15	.50 PDT	<b>7</b> 30,00	0 or More Cus 10 - 49,999 Cu	stomers			
Ended:	Date:		Time:		Spec	ncident ≥ 1,000 ial Offices/Fac	0 lines ilities			
Duration (in n	ninu¦tes	<b>s)</b> :				111 Major/Medium / NCS Request	Airport			
Geographic Area Affected: Central Valley, California										
Estimated Customers Affected: 1,802										
Type(s) of Se	] Oper	Affected: ator Services national		change	IntraLATA   Switched Ar FAA	☐ InterLATA ccess (interoffi ☐ All	☐ 800 ce)			
Estimated Blocked Calls: Under Investigation										
Apparent or Known Cause of the Outage: At 15:50 PDT, on Monday, August 14, 2000 a wildfire burned two exchange cables that had 1,802 working pairs South of Union School Road between Old Oregon Trail and Interstate 5 near the town of Central Valley, California. The exchange cables serve three pair gain facilities supporting eleven SLC 96 (Subscriber Loop Carrier) and seven SLC Series 5 systems. Restoration crews were prevented from entering the area until Tuesday, August 15. Restoration efforts are still underway.										
Name and Type of Equipment Involved: Copper Exchange Cables										
Specific Part of Network Involved: Local										
Methods used to Restore Service: Under Investigation										
Steps Taken to Prevent Recurrence: Under Investigation										
Prepared by Date submit	: Jim L ted: 08	ankford 3/17/2000		Teleț	hone: 210 Time: 10:3					